Property Inspection Report



1234 Texas Parkway, The Woodlands, TX 77380 Inspection prepared for: Jane Doe Real Estate Agent: -

Date of Inspection: 12/12/2019 Time: 8:30 AM Age of Home: 2019 Size: 3256 sqft Weather: Sunny This is a Phase 1 home inspection following the TREC Standards of Practice.

> Inspector: Travis Kepp License #20608 Phone: 713-817-3957 Email: travis@southernstarinspections.com www.SouthernStarInspections.com



Southern Star Insp	pections, LLC	1234 Texas Par	kway, The Woodlands, דא
	PROPERTY INS	PECTION REPO	RT
Prepared For:		Jane Doe	
		(Name of Client)	
Concerning:	1234 Texas	Parkway, The Woodlands	s, TX 77380
-	(Address	or Other Identification of Inspected P	roperty)
By:	Travis Kepp, L	icense #20608	12/12/2019
	(Name and License	Number of Inspector)	(Date)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical
- receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- · lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Important Reminders:

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety, we recommend that licensed contractors evaluate and repair any critical concerns and defects. This report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide. Note: All directions given in this report (i.e. left, right, front, rear) are to be taken as if standing on the street facing the front of the building or, when appropriate, the system or component being inspected. Stored items, furniture, personal belongings, vehicles, etc. all obscure and impede the inspections process. When any of these items are present, client should assume that portions of the structure, systems and components were probably concealed or otherwise overlooked. Client should not assume that every deficiency was identified, recognized, or otherwise reported.

What We Inspect:

A Home Inspection is a **non-invasive visual examination** of a residential dwelling, performed for a fee, which is designed to identify observed material defects within specific components of said dwelling. Components may include any combination of mechanical, structural, electrical, plumbing, or other essential systems or portions of the home, as identified and agreed to by the Client and Inspector, prior to the inspection process.

A home inspection is intended to assist in evaluation of the overall condition of the dwelling. The inspection is based on observation of the visible and apparent condition of the structure and its components on the date of the inspection and **not the prediction of future conditions**.

A home inspection will not reveal every concern that exists or ever could exist, but only those material defects observed on the day of the inspection.

A material defect is a condition with a residential real property or any portion of it that would have a significant adverse impact on the value of the real property or that involves an unreasonable risk to people on the property. The fact that a structural element, system or subsystem is near, at or beyond the end of the normal useful life of such a structural element, system or subsystem is not by itself a material defect.

An Inspection report shall describe and identify in written format the inspected systems, structures, and components of the dwelling and shall identify material defects observed. **Inspection reports may contain recommendations regarding conditions reported or recommendations for correction, monitoring or further evaluation by professionals, but this is not required.**

This is NOT a Wood Destroying Insect Inspection. If requested, Southern Star Inspections provides reputable wood destroying insect inspectors for the client to contact for more information regarding their services. **Summary page info:**

On the Summary Page you will find, in **RED**, a brief summary of any **CRITICAL** concerns of the inspection, as they relate to Safety and Function. Examples would be bare electrical wires, or active drain leaks. If items are marked **RED** and/or "deficient", we recommend an evaluation of the entire system by a qualified technician or professional. The


complete list of items noted is found throughout the body of the report, including Normal Maintenance items. For your safety and liability, we recommend that you hire only licensed contractors when having any work done. If any area has been remodeled or part of an addition, we recommend that you verify the permit and certificate of occupancy. This is important because our inspection does not guarantee the integrity of any work that was done without a permit. Depending upon your needs and those who will be on this property, items listed in the **body** of the report may also be a concern for you; be sure to read your Inspection Report in its entirety.

Note: If there are no comments in **RED** below, there were no **CRITICAL** system or safety concerns with this property at the time of inspection.

Southern Star In	spections, LLC	1234	Texas Parkway,	The Woodlands, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D			D-Denoient	
	I. STR		MS	

1234 Texas Parkway, The Woodlands, TX Southern Star Inspections, LLC I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D **X A.** Foundations Х Type of Foundation(s): Slab on Grade - Post Tension Cable Comments: This inspection is a visual review of the foundation and represents the opinion of the inspector, based solely on the inspector's personal experience with similar homes. The inspector does not pull up floor coverings, move furniture, measure elevations or propose repairs. The inspector does not enter crawl space areas less than 18". Minor settlement or "hairline" cracks in drives, walks or even foundations are normal to properties of any age. They should, however, be monitored for expansion and sealed as necessary. Homes built with slab and/or post tension cable foundation construction may have heating ductwork, plumbing, gas, and electrical lines running beneath the slab. As it is impossible to visually inspect these items, they are specifically excluded from the scope of this inspection. The opinion stated below in no way addresses future foundation movement or settlement. If items are marked in Red, marked as "Deficient", and/or you should you have any concern regarding the foundation, it is recommended you have a complete evaluation prior to close. Note: The foundation performance opinion stated below neither in any way addresses future foundation movement or settlement, nor does it certify floors to be level. Soil in the Houston Texas area is known to be unstable and unpredictable. Due to the expansive nature of the soil in this area, no warranty against future movement can be made. This inspector is not responsible for defects in the slab in areas that are not visible for inspection. The inspector does not perform any engineering studies or measurements such as geological, and hydrological stability test, soils conditions reports; or any form of engineering analysis. Should you have present or future concerns regarding the foundation's condition, you are strongly advised to consult with a licensed Professional Structural Engineer for further evaluation. Interior Beams -Width = approx. 12" Depth = approx. 24" The interior beam depth and width were evaluated for depth at ten (10) random points and each were within acceptable limits. Exterior Beams -Width = approx. 12" Depth = approx. 24" The exterior beam depth and width were evaluated for depth at ten (10) random points and each were within acceptable limits. A string line is in place at the time of the inspection. All foreign debris should be removed from within the foundation area prior to poring concrete. Check all. Various drain lines are exposed and not properly coated with mastic at the time of the inspection. Check all. All breaks, tears, rips (damaged areas or voids) in the Post-Tensioning Cable sheathing material shall be repaired with the appropriate tape prior to concrete placement. Conduit material is not properly secure in place at the time of the inspection. Check all. Cable Quantity -REI 7-5 (05/4/2015) Page 5 of 15

Southern	Star I	Inspections,	LLC



Remove all debris from within foundation

Remove all debris from within foundation

Missing cable at rear elevation

I=Inspected	 =	Inspected
-------------	------------	-----------

NI=Not Inspected

NP=Not Present

D=Deficient

NP NI D



Cable not secure in place at front elevation



Cable not secure in place at garage



Cable chair not properly seated





Cable chair not properly seated Cable chairs not properly seated



Cables not raised off beam



Cables not raised off beam at left elevation



Cables not raised off beam




Cable not raised off pad



Cables not raised off pad





Drain line not coated with mastic Drain line not coated with mastic

I=Inspected NI=Not Inspected D=Deficient NP=Not Present NI NP D Repair torn/damaged poly Repair/seal torn poly Repair/seal torn poly



Repair/seal torn poly



Poly not sealed/secure in place





Poly not sealed/secure in place



Poly not sealed/secure in place



Cables in contact with drain at left elevation



Cables in contact with drain at rear elevation



Cables in contact with drain at Cable in contact with form at left Cable in contact with form at rear right elevation



right elevation



elevation

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



at left elevation





at rear elevation



Cable clamp not secure in place Cable clamps not secure in place Conduit material not secure in





place



Evidence of cave-in at rear elevation




Evidence of cave-in at rear elevation



Evidence of cave-in at right elevation



Damaged drain line at left elevation



Southern Star II	nspections, LLC	1234 Te	exas Parkway,	The Woodlands, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	C. Roof Covering I	Materials		
	examine the roof imme not speculate on the re- inspection does not ad free at time of the insp- organic debris all affect determine the roof shir shingles. It has been d accessible roofing suff attic only. Tiled roofing marked as "Deficient", covering material, it is roof covering system p	Ilars areas of the house, we ediately prior to closing emaining life expectance dress future leaks nor ection. Adequate attic w ection. Adequate attic w the life expectancy of ngle fastener pattern by letermined that lifting ro faces are inspected from surfaces are not walke and/or should you have recommended that you	on the home. The cy of the roof cove does it certify that ventilation, solar/v a roof. The inspe / lifting a random of shingles can c m the ground with ed on. If items are any concern reg i have a complete	e inspector does ering. This t the roof is leak- wind exposure, and ector did not sampling of eause damage. Non binoculars and e marked in Red, garding the roof e evaluation of the
	D. Roof Structures	and Attics		
	Comments: Not all are limited inspection of wi in Red, marked as "De roof structure, it is reco structure prior to close	Thickness of Vertical Ir as of an attic are visible hat can be viewed from ficient", and/or should commended you have a	e due to lack of ac a safe platform. you have any con complete evaluat	<i>If items are marked ncern regarding the tion of the roof</i>
	E. Walls (Interior a	nd Exterior)		
	stored items are not m the inspectors scope to they pertain to structur does not cover any iss not limited to, lead bas siding, but especially c and seams must rema- items are marked in Re regarding the walls, it i to close.	ed walls will be inspected oved by the inspector of o determine the condition ral performance or mois sues that are considered sed paint, asbestos, rad composition or hardboa in sealed (especially th ed, marked as "Deficient is recommended a composition nis time. Will be inspe	during the inspect on of the wall cov sture penetration. d to be environme lon, mold, mildew rd siding must be re lower courses a nt", and/or should plete evaluation b	tion. It is beyond rerings except as This inspection ental, such as, but or funguses. All closely monitored at ground level). If you have concern be conducted prior

Southern Star Inspections, LLC		1234 Te	exas Parkway,	The Woodlands, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	F. Ceilings and Flo	ors		
	environmental, such as mold, mildew or fungus and/or should you have recommended a comp to close.	rior floors are visible an erings, furniture, stored is inspection to remove mine the condition of the to the structural perforr of cover any issues that s, but not limited to, lead ses. If items are marked e concern regarding the	I items, construct any floor coveri- me interior ceiling mance and/or mo t are considered d based paint, as d in Red, marked e ceilings and floors eilings and floors	tion debris, etc. It is ng. The inspection or floor covering bisture penetration. to be sbestos, radon, as "Deficient", ors, it is be conducted prior
	G. Doors (Interior a	and Exterior)		
	Comments: It is comme bind mildly or that the I locks re-keyed after clo marked in Red, marked the doors, it is recomme close.	atches may need adjus osing and before movin d as "Deficient", and/or	stment. We recon g in to your new should you have evaluation be co	nmend having all home. If items are concern regarding nducted prior to
	H. Windows			
	Window Types: Comments: Inspection device is beyond the se broken without having panes. Obviously fogge inspection is not possil surfaces and/or rain at around all interior and items are marked in Re regarding the windows windows be conducted • Not inspected at the	cope of the inspector. I a visible amount of con ed windows are noted w ble due to some light co time of inspection. Rec exterior windows to det ed, marked "Deficient", , it is recommended the	Double pane wind densation build- when observed b onditions, installe commend periodi er moisture and and/or should yo at a complete eva	dow seals may be up between the ut a complete d screens, dirt on ically sealing insect intrusion. If ou have concern aluation of the
	I. Stairways (Interio	or and Exterior)		
	Comments: This section guardrails, handrails, e and/or should you have a complete evaluation • Not inspected at th	tc. If items are marked e concern regarding the	in Red, marked a stairways, it is r ducted prior to c	as "Deficient", ecommended that lose.

Southern Star II	nspections, LLC	1234	Texas Parkway,	The Woodlands, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	J. Fireplaces and	Chimneys		
	for proper draft, cond inspector is required fireplace/chimney on of the inspector. If ite you have concern reg complete evaluation qualified contractor.	and the scope for the in luct a smoke test or ve to perform an inspection ly. Freestanding wood ms are marked in Red garding the fireplace and of the fireplace and ch this time. Will be insp	rify the integrity of a on on the visible co burning stoves are , marked as "Defici nd chimney, it is rea imney be conducte	the flue. The mponents of the beyond the scope ent", and/or should commended that a d prior to close by a
	K. Porches, Balconies, Decks, and Carports			
	structures or waterfro marked as "Deficient porches, decks, carp conducted prior to clo	and the scope of the in- ont structures and equi ", and/or should you ha orts, etc, it is recomme ose. this time. Will be ins	pment. If items are ave concern regard ended a complete e	marked in Red, ling the exterior valuation be
	L. Other			
	Materials: Comments:			
Right elevat	tion of home	Left elevation of home		r clean out at front t elevation

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	

I NI NP D



Water meter location at front left corner



Main water line entry to home

Report Summary

STRUCTURA	L SYSTEMS	
Page 6 Item: A	Foundations	 Cable Quantity - Front to Back = 38 Left to Right = 41 Missing 1 cable at the rear elevation of the home at the time of the inspection. Check all. The dead or fixed tendon ends were not properly secure in place at the front and left elevation of the home at the time of the inspection. All nails for post tension cables should be secure to form boards. Check all. Several cables were in contact with bottom of the beams and/or pads at the time of the inspection. Where tendons cross perpendicular beams, chairs should be placed within 6 in. (150 mm) of each side of the beam. Additional chairs should be installed near cross beams to ensure support during placement of the concrete. All chairs should be properly placed under cables. Check all. Several areas of the poly/plastic were not properly secure in place and/or sealed at the time of the inspection. To prevent cement slurry from entering below vapor barriers, all holes and open seams in the vapor barrier must be repaired with approved tape. Check all. Clearance between tendons and drain waste vents were less than 3" in several locations. A minimum of 3 in. should be maintained around all piping. Chairs should be installed at each vent to maintain minimum clearance during placement of the concrete. Check all. Fixed-end of tension cables were in direct contact with the edge of the form in numerous locations. Approximately 3/4in. of space between the cable end and the form board should be present. The tendons should be pulled taught so that there is full coverage during the placement of the concrete. Check all. Pocket formers should be flush and secure against form boards spirot to pouring the foundation concrete. Metal clamps (cat-heads) attached to live end of tension cables should be flush and secure against form boards spirot to pouring the foundation concrete. Metal clamps (cat-heads) attached to live end of tension cables should be flush and secure against form boards prior to pouri