Property Inspection Report



1234 Texas Ave., Cypress, TX 77433 Inspection prepared for: John Doe Real Estate Agent: -

Date of Inspection: 1/21/2020 Time: 8:30 AM Age of Home: 2020 Size: 4400 sqft Weather: Sunny

Home is a two story with an attached four car garage. Clent present at completion of inspection.

Inspector: Travis Kepp License #20608 Phone: 713-817-3957 Email: travis@southernstarinspections.com www.SouthernStarInspections.com



Southern Star Inspections, LLC		1234 7	Texas Ave., Cypress, TX
	PROPERTY INSPE	CTION REPOR	Т
Prepared For:		John Doe	
·	(Name of Client)		
Concerning:	Concerning: 1234 Texas Ave., Cypress, TX 77433		433
(Address or Other Identification of Inspected Property)			erty)
By:	Travis Kepp, Licen	ise #20608	1/21/2020
	(Name and License Number	er of Inspector)	(Date)

PURPOSE, LIMITATIONS AND INSPECTOR / CLIENT RESPONSIBILITIES

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.texas.gov.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is NOT required to turn on decommissioned equipment, systems, utility services or apply an open flame or light a pilot to operate any appliance. The inspector is NOT required to climb over obstacles, move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector shall indicate, by checking the appropriate boxes on the form, whether each item was inspected, not inspected, not present or deficient and explain the findings in the corresponding section in the body of the report form. The inspector must check the Deficient (D) box if a condition exists that adversely and materially affects the performance of a system or component or constitutes a hazard to life, limb or property as specified by the TREC Standards of Practice. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing components, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards or Deficiencies below.

THIS PROPERTY INSPECTION IS NOT A TECHNICALLY EXHAUSTIVE INSPECTION OF THE STRUCTURE, SYSTEMS OR COMPONENTS. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods.

Promulgated by the Texas Real Estate Commission (TREC) P.O. Box 12188, Austin, TX 78711-2188 (512) 936-3000 (http://www.trec.texas.gov).

1234 Texas Ave., Cypress, TX

Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- malfunctioning, improperly installed, or missing ground fault circuit protection (GFCI) devices for electrical
- receptacles in garages, bathrooms, kitchens, and exterior areas;
- malfunctioning arc fault protection (AFCI) devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- · lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Important Reminders:

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion

of the structure; inspection **may be limited** by vegetation and possessions. Depending upon the age of the property, some items like GFI outlets may not be installed; **this report will focus on safety and function, not current code**. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety, we recommend that licensed contractors evaluate and repair any critical concerns and defects. This report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide. Note: All directions given in this report (i.e. left, right, front, rear) are to be taken as if standing on the street facing the front of the building or, when appropriate, the system or component being inspected. Stored items, furniture, personal belongings, vehicles, etc. all obscure and impede the inspections process. When any of these items are present, client should assume that portions of the structure, systems and components were probably concealed or otherwise overlooked. Client should not assume that every deficiency was identified, recognized, or otherwise reported.

What We Inspect:

A Home Inspection is a **non-invasive visual examination** of a residential dwelling, performed for a fee, which is designed to identify observed material defects within specific components of said dwelling. Components may include any combination of mechanical, structural, electrical, plumbing, or other essential systems or portions of the home, as identified and agreed to by the Client and Inspector, prior to the inspection process.

A home inspection is intended to assist in evaluation of the overall condition of the dwelling. The inspection is based on observation of the visible and apparent condition of the structure and its components on the date of the inspection and **not the prediction of future conditions**.

A home inspection will not reveal every concern that exists or ever could exist, but only those material defects observed on the day of the inspection.

A material defect is a condition with a residential real property or any portion of it that would have a significant adverse impact on the value of the real property or that involves an unreasonable risk to people on the property. The fact that a structural element, system or subsystem is near, at or beyond the end of the normal useful life of such a structural element, system or subsystem is not by itself a material defect.

An Inspection report shall describe and identify in written format the inspected systems, structures, and components of the dwelling and shall identify material defects observed. **Inspection reports may contain recommendations regarding conditions reported or recommendations for correction, monitoring or further evaluation by professionals, but this is not required.**

This is NOT a Wood Destroying Insect Inspection. If requested, Southern Star Inspections provides reputable wood destroying insect inspectors for the client to contact for more information regarding their services. **Summary page info:**

On the Summary Page you will find, in **RED**, a brief summary of any **CRITICAL** concerns of the inspection, as they relate to Safety and Function. Examples would be bare electrical wires, or active drain leaks. If items are marked **RED** and/or "deficient", we recommend an evaluation of the entire system by a qualified technician or professional. The

complete list of items noted is found throughout the body of the report, including Normal Maintenance items. For your safety and liability, we recommend that you hire only licensed contractors when having any work done. If any area has been remodeled or part of an addition, we recommend that you verify the permit and certificate of occupancy. This is important because our inspection does not guarantee the integrity of any work that was done without a permit. Depending upon your needs and those who will be on this property, items listed in the **body** of the report may also be a concern for you; be sure to read your Inspection Report in its entirety.

Note: If there are no comments in **RED** below, there were no **CRITICAL** system or safety concerns with this property at the time of inspection.

Southern Star I	Inspections, LLC		1234 Texas Ave., Cypress, T			
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient			
I NI NP D)					
I. STRUCTURAL SYSTEMS						
	A. Foundations					
 Slab on Grade - Post Tension Cable Comments: This inspection is a visual review of the foundation and represents the opinion of the inspector, based solely on the inspector's personal experience with similar homes. The inspector does not pull up floor coverings, move furniture, measure elevations or propose repairs. The inspector does not enter crawl space areas less than 18". Mior settlement or "hairline" cracks in drives, walks or even foundations are normal to properties of any age. They should, however, be monitored for expansion and sealed as necessary. Homes built with slab and/or post tension cable foundation construction may have heating ductwork, plumbing, gas, and electrical lines running beneath the slab. As it is impossible to visually inspect these items, they are specifically excluded from the scope of this inspection. The opinion stated below in no way addresses future foundation movement or settlement. If items are marked in Red, marked as "Deficient", and/or you should you have any concern regarding the foundation, it is recommended you have a complete evaluation prior to close. Performance Opinion: TI SI MY OPINION that at the time of this inspection the visible areas of the foundation appears to be supporting the structure and immediate significant repair needs are not evident. The structure should be monitored for signs of differential movements of foundations can occur because of the structures and differential movements of foundations can occur because of the structure action columns at the time of the inspection. Future performance of the structure action columns at the time of the inspection. Recommend removing so not to attract wood destroying insects. Foundation scan occur because of the structure action columns at the time of the inspection. Recommend removing so reven foundation at repair needs are nor "maintine" cracks in drives, walks or even foundation sate normal to properties of any age. The cracksfiract						
Remove wood a	at rear left column Fo	oundation chipped at garage wall	Hairline cracks in garage			

Southern Star Inspections, LLC 1234 Texas Ave., Cypress, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient NI NP D **B. Grading & Drainage** Х Х Comments: Grading and drainage are probably the most significant aspects of a property, simply because of the direct and indirect damage that moisture can have on structures. It is advisable to maintain at least four inches of clear area between the ground and masonry and six inches of clearance between ground and wood siding. Proper drainage is critical to the performance of the foundation. All grades should drop away from the structure at a rate of 6 inches per 10 feet. Sprinkler systems if not properly installed and adjusted to provide uniform and proper levels of moisture content in the soil, can lead to differential foundation movement. Determining flood plains is beyond the scope of this inspection. The seller/builder may have more information concerning this subject. If items are marked in Red, marked as "Deficient", and/or should you have any concern regarding the Grading or Drainage, it is recommended you have a complete evaluation of the drainage system prior to close. Partial gutter system is installed at time of inspection. Gutters are essential in preserving the integrity of the foundation and grading around it. Gutters help divert storm water away from the foundation in a uniform manor. Recommend installing a full home gutter system and removing debris from gutters periodically so that moisture can be diverted away from foundation walls. Recommend open end of splash block be placed away from the home to deter standing water. Check all. Gutter downspouts are connected directly to below grade drainage pipe. Termination location is unknown. It is beyond the scope of the inspection to determine if they drain and flow properly. Subsurface and/or french drains are present at time of inspection. Determining if these drains are acting as intended and/or serviceable is beyond the scope of the inspection. Recommend keeping these drain covers free of debris and grass clippings. Excessive moisture and/or standing water was observed at the left of the property at the time of the inspection. The grading should promote the flow of storm water away from the foundation and off the lot in a timely manner. Some options might be but not limited to: additional gutters, improved swale, surface drains, french drains, or sub surface drains. Gutters have construction and/or vegetation debris present that can possibly clog the gutter down spouts and cause moisture penetration. Recommend periodically cleaning all gutters so that water is diverted away from structure as intended. Check all. Million Harris to Winds Wildian Sin Open end away from structure Splash block Keep drains free of debris

```
I=Inspected
                            NI=Not Inspected
                                                                 NP=Not Present
                                                                                                     D=Deficient
             NP
       NI
                     D
                                                          Construction debris present
                                                                                                               Vegetation debris present
 Excessive moisture at left elevation
                          C. Roof Covering Materials
 Х
                           Type(s) of Roof Covering:

    Asphalt shingles

                           Viewed From:

    Accessible areas of the roof

                           Comments: As with all areas of the house, we recommend that you carefully examine the roof
                           immediately prior to closing on the home. The inspector does not speculate on the remaining life
                           expectancy of the roof covering. This inspection does not address future leaks nor does it certify
                           that the roof is leak-free at time of the inspection. Adequate attic ventilation, solar/wind exposure,
                           and organic debris all affect the life expectancy of a roof. The inspector did not determine the roof shingle fastener pattern by lifting a random sampling of shingles. It has been determined that
                           lifting roof shingles can cause damage. Non accessible roofing surfaces are inspected from the
                          ground with binoculars and attic only. Tiled roofing surfaces are not walked on. If items are
marked in Red, marked as "Deficient", and/or should you have any concern regarding the roof
covering material, it is recommended that you have a complete evaluation of the roof covering
```

system prior to close.

 Maintenance of roof covering is necessary on an annual or semi-annual basis. This generally consists of replacing loose or missing shingles, replacing ridge caps, and sealing exposed nails as necessary. Life expectancy of a composition roof can range from 15 - 25 years, depending on the quality of the material. Shingles labeled as 30-40 year life expectancy, last approximately 20-25 years in the Houston area. It is best to replace a roof when signs of cracking, curling edges, brittle shingles, or signs of granular loss are observed.

Construction/mud debris present at various locations of the roof covering at the time of the inspection. Check all.

Damaged/torn shingle at the front elevation of the roof covering at the time of the inspection. Damaged shingles should either be properly sealed and or replaced to deter moisture intrusion and or further damage. Check all.



Debris/mud on roof covering



Debris/mud on roof covering

Debris/mud on roof covering

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
		Damaged/torn shingle	
X X X	D. Roof Structures	and Attics	
	 Unknown Depth. The in drywall Comments: Not all areas of what can be viewed from a and/or should you have an complete evaluation of the Viewed From: Accessibile Some framing member accessible and/or visible appeared to be construct Access to the attic spa attic that is greater that 3 accessible. Inspector obsusing thermal imaging ca 	-16 inches deep kness of Vertical Insulation: spector is unable to detern of an attic are visible due to la safe platform. If items are may concern regarding the roof roof structure prior to close. Ile Areas of the Attic rs within the garage and att for inspection. From the a ted and functioning as inter ace above the study is not served higher than normal amera. It appears batts and	nine the depth of the insulation behind ock of access. This is a limited inspection of parked in Red, marked as "Deficient", structure, it is recommended you have a tic space of the home are not ccessible attic space, the roof structure nded at the time of the inspection. present at the time of the inspection. An nches of headroom should be readily temperature difference at this location /or blown-in insulation is not installed all areas have an equal R-value has

Access to attic space not present

Evidence of temperature difference study ceiling/walls

Evidence of temperature difference study ceiling/walls

Southern Star Ins	spections, LLC		1234 Texas Ave.,	Cypress, T
	-			
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
			D-Dencient	
I NI NP D				
	E. Walls (Interior an	d Exterior)		
 X X E. Walls (Interior and Exterior) Wall Materials: Exterior walls are Stucco/Stone/Siding Material Interior walls are Stucco/Stone/Siding Material Interior walls are Stucco/Stone/Siding Material Therior walls are stucco/Stone/Siding Material Statistic exposed walls will be inspected. Furniture, personal items, and stored items are not moved by the inspector during the inspector. It is beyond the inspectors scope to determine the condition of the wall coverings except as they pertain to structural performance or moisture penetration. This inspection does not cover any issues that are considered to be environmental, such as, but not limited to, lead based paint, asbestos, radon, mold, mildew or funguses. All siding, but especially composition or hardboard siding must be closely monitored and seams must remain sealed (especially the lower courses at ground level). If items are marked in Red, marked as "Deficient", and/or should you have concern regarding the walls, it is recommended a complete evaluation be conducted prior to close. Minor caulk and paint touch ups needed at exterior of the home. Recommend sealing all gaps and/or voids in siding material. All exposed nall heads securing siding material to structure should be sealed as needed. Check all. Seal around all gaps of electrical and/or plumbing penetrations through cabinets and plumbing pipes in cabinets, at electrical outlets and fixtures, vents. Minor drywall repair and paint touch ups are needed at various locations of the home. Check all. Seal all gaps where the exterior cladding material intersects with one another to deter moisture and insect intrusion. Some areas include but not limited to: exterior siding to stucco, stone to stucco. Check all. Seal around all gaps of electrical an				
Seal material in	tersections Sea	al material intersections	Seal material inters	sections

Seal material intersections

Seal all exterior penetrations

Seal all exterior penetrations

NI=Not Inspected

NI NP D Seal all exterior penetrations

NP=Not Present

Seal all exterior penetrations



Drywall/paint touch ups needed



Seal shower corners/Intersections



I=Inspected


Seal all exterior penetrations



Seal shower corners/Intersections

Page 9 of 33







1234 Texas Ave., Cypress, TX

D=Deficient

Southern Star	Inspections, LLC		1234 Texas Ave., Cypress, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP [)		
	F. Ceilings and Flo	oors	
	coverings, furniture, stored to remove any floor covering interior ceiling or floor cover moisture penetration. This environmental, such as, but funguses. If items are mark regarding the ceilings and a floors be conducted prior to • Minor drywall repair ar Check all. • Carpet flooring is not p considered a trip hazard	items, construction debris, e ag. The inspection is not requiring except as they pertain to inspection does not cover and t not limited to, lead based p red in Red, marked as "Defice floors, it is recommended a co- o close. ad paint touch ups needed properly secure in place at and is in need of repair. Ch to the secure at upstairs landing the secure at upstairs landing	
	G. Doors (Interior	and Exterior)	
	 that the latches may need a before moving in to your need should you have concern to conducted prior to close. Recommend keeping of limit moisture/insect intro Recommend boring hore enable deadbolts to fully Missing weatherstrippi Flush bolt at the back of inspection. Missing trim of exterior door glass inspection. Check all. Exterior door leading to the back of the section of the section of the section of the section. 	adjustment. We recommend we home. If items are marked egarding the doors, it is reco- exterior door thresholds an usion. Check all. engage. Check all. ing at the back door at the door is not functioning/unl cover. Check all. eert screw caps/covers are o the courtyard does not c	yes that some doors may bind mildly or having all locks re-keyed after closing and d in Red, marked as "Deficient", and/or mmended that a complete evaluation be ad bottom of door jambs/trim sealed to ack and exterior courtyard doors to time of the inspection. Check all. ocking as intended at the time of the not present at the time of the lose tightly at the time of the e tight against strike plate when closed.

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D



Keep door thresholds/jambs sealed



Flush bolt inoperable at back door



Seal rear elevation threshold



Missing screw caps/covers at back door



Missing weatherstripping at back door



Courtyard door not closing tight



Bore deadbolt hole

H. Windows

Window Types:

- Window frames are made of Vinyl
- Windows are Single Hung

Comments: Inspection of storm windows, awnings, shutters, or other security device is beyond the scope of the inspector. Double pane window seals may be broken without having a visible amount of condensation build-up between the panes. Obviously fogged windows are noted when observed but a complete inspection is not possible due to some light conditions, installed screens, dirt on surfaces and/or rain at time of inspection. Recommend periodically sealing around all interior and exterior windows to deter moisture and insect intrusion. If items are marked in Red, marked "Deficient", and/or should you have concern regarding the windows, it is recommended that a complete evaluation of the windows be conducted prior to close.

• Windows that were tested functioned as intended at the time of the inspection. Recommend sealing around all interior and exterior windows to deter moisture and insect intrusion as needed. Check all.

Х

Southern Star In	spections, LLC		1234 Texas Ave., Cypress, T
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	I. Stairways (Interi	or and Exterior)	
	etc. If items are marked in the stairways, it is recomm to close.	Red, marked as "Deficient", ended that a complete evalu	es related to railings, guardrails, handrails, and/or should you have concern regarding ation of the stairways be conducted prior
	• Stair treads and risers	were installed and acting a	as intended at time of the inspection.
x	J. Fireplaces and	Chimneys	
	Types: • Natural Gas • Fireplaces are prefabric Comments: It is beyond the conduct a smoke test or very inspection on the visible co stoves are beyond the scop and/or should you have con- complete evaluation of the contractor. • Front elevation courty used to test fireplace and • Living room fireplace to	e scope for the inspector to the erify the integrity of the flue. To emponents of the fireplace/ch be of the inspector. If items a ncern regarding the fireplace fireplace and chimney be co and fireplace has is operate I is operating as intended a has a glass front and is operate	n the Living Room est the Fireplace/Chimney for proper draft, The inspector is required to perform an aimney only. Freestanding wood burning are marked in Red, marked as "Deficient", and chimney, it is recommended that a inducted prior to close by a qualified ed by a switch on the wall. Switch was at the time of the inspection. erated by a remote control. Remote as intended at the time of the
Fireplace	e operated by switch on wall	Firep	blace operated by remote control
		nies, Decks, and Ca	. ,
	Comments: It is beyond the structures and equipment. have concern regarding the evaluation be conducted pi	e scope of the inspector to re If items are marked in Red, r e exterior porches, decks, ca rior to close. im material is not sealed/p	eport on detached structures or waterfront marked as "Deficient", and/or should you rports, etc, it is recommended a complete ainted at the upper front porch at the

Southern Star Inspections, LLC 1234 Texas Ave., Cypress, TX D=Deficient I=Inspected NI=Not Inspected NP=Not Present NI NP D Siding material not painted at front porch L. Other Х Х Materials: Flatwork Fence Granite Comments: Driveway flatwork expansion joint is not cut/properly removed at the front elevation of the home at the time of the inspection. Check all. • Fence picket is missing at the rear left elevation of the property at the time of the inspection. Check all. Soap dispenser or cover/cap is not present at the kitchen countertop at the time of the inspection. Right elevation of home Left elevation of home Rear elevation of home



Flatwork expansion joint not removed



View from above




Missing fence picket at rear left elevation

Southern Star Inspections, LLC 1234 Texas Ave., Cypress, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D



Missing decorative cap/cover



Remove temporary meter and pole

Southern Star I	nspections, LLC		1234 Texas Ave., Cypress, T>
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	B. Branch Circuits	s, Connected Devic	es, and Fixtures
	kitchen, and all exterior ou implemented, it is not requi- but are not limited to: cable systems, electric gates and the test button on each det Smoke alarms are not che marked as "Deficient", and recommended a complete • Doorbell operated nor • Smoke detectors were the time of the inspection detectors. Recommend c • GFCI receptacle cover Check all. • Light fixtures over the Inspector was not able to • GFCI (ground fault circ functioning/resetting at t receptacles are required backsplash, and bathroo • Missing receptacle cover che inspection. • Light bulb is missing a Recommend installing bu home. Check all. • Four way circuit/switc the inspection. Switches switches should be able • The living room fan ex inspection. Recommend	Circuit Interrupter (GFCI) out tlets/wet areas. If home was ired to upgrade but is highly e, telephone, computer, spe d doors, yard and tree lightin tector. Smoke detectors are cked when a security system for should you have concern evaluation be conducted pri- mally at the time of the ins- not manually tested due hanging batteries and tes s are missing identifying s showers/tubs are require or identify proper tag at the cuit interrupter) receptacle he time of the inspection. in all wet areas. Required ms. Check all. ver plate within the garage resent at the right and left at the dining room light fix ulb and checking function hes for the main kitchen li have to be in a certain po to work independently of cessively wobbled/shook balance and/or tightening te system evaluation and	spection. to the security system being present at rity company monitors the smoke sting the smoke detectors upon move in. sticker at the time of the inspection. d to be rated for wet and/or damp areas. e time of the inspection. es at the outdoor kitchen are not Ground Fault Circuit Interrupter (GFCI) areas include: exterior, garage, kitchen e at the time of the inspection. Check all. side of the kitchen island left at the time ture at the time of the inspection. of light fixture prior to closing on the isjtion for the other to function. These one another. when operated at the time of the






Missing sticker at GFCI receptacles

Missing receptacle cover in garage

I=Inspected NI=Not Inspected **D**=Deficient NP=Not Present NI NP D Receptacle not present at island Receptacke not present at island Missing light bulb at light fixture

Living room fan excessively wobbles/shakes



Furnace/Air handler located in upper attic space

Furnace burner ports

Furnace/Air handler located in upper attic space

1234 Texas Ave., Cypress, TX

I=Inspected

NI=Not Inspected

NP=Not Present


D=Deficient

I NI NP D

Х



Furnace burner ports



Type of Systems:

• 2 Central Forced-Air

• A/C condensing units are located on the elevation of the home

Comments: Inspection of the HVAC equipment is by operation of system only. Testing for leaks, efficiency, or disassembling equipment are not within the scope of the inspection. Cooling equipment is not checked when the outside temperature is below 60 °F because of possible damage to the compressor. Humidifiers, motorized dampers, electronic air filters and programmable thermostats are not inspected. Window air conditioning units are not tested. We recommend the cooling system be completely serviced before each cooling season and the primary condensate drain line be flushed with a chlorine bleach/water solution every 2 months during the cooling season to prevent clogging. If items are marked in Red, marked as "Deficient", and/or should you have concern regarding the cooling equipment it is recommended that a complete evaluation of the cooling equipment be conducted prior to close.

• A/C - Lennox

- model# = 14ACX-060-230-16
- serial# = 1919G03394
- manufacture year = 2019
- A/C Lennox
- model# = 14ACXS024-230A21
- serial# = 1919A43916
- manufacture year = 2019

• Recommend a storm water splash guard be installed at roof edge to divert water away from the A/C condensing unit.

• Primary condensation drain lines are terminated to a bathroom vanity drain and the secondary drain lines are terminated to the exterior of the home through the exterior soffit. If condensation is seen dripping from the secondary drain lines it is recommended to turn off the system and contact a licensed HVAC technician.

• *Visual inspection of the cooling equipment components only. The A/C systems are not tested for proper operation when the outside air temperature is 65 degrees or less. The colder temperature makes it difficult to determine proper function and can potentially damage components of an air conditioner. It is always recommended to have a licensed HVAC technician conduct a complete system evaluation of the HVAC equipment prior to the first use of the season. Recommend following the manufacture care and maintenance instructions.

The A/C refrigerant line insulation at the condensing unit is damaged/torn. Refrigerant line exposed at the time of the inspection. Recommend repairing and/or replacing.
Seal the gaps where the refrigerant lines enter the evaporater coil cabinet and where the condensing drain lines exit the <u>evaporator coil</u> cabinet to deter loss of conditioned air within the attic space. Check all.

```
I=Inspected
```

```
NI=Not Inspected
```

NP=Not Present

D=Deficient

I NI NP D



Recommend splash guard over condensing units



Secondary A/C drain line at rear elevation



Secondary A/C drain line at rear right elevation



Humidifier drain line at rear left elevation



Damaged/torn refrigerant line insulation




Primary A/C drain line



Seal refrigerant/drain lines at evaporator coil cabinet



Seal drain lines at evaportor coil cabinet




Southern Star Inspections, LLC 1234 Texas Ave., Cypress, TX I=Inspected NI=Not Inspected NP=Not Present D=Deficient I NI NP D


HVAC duct work in contact with one another

Southern Star Inspections,	LLC		1234 Texas Ave.,	Cypress, TX		
I=Inspected NI=Not In	spected NP=I	Not Present	D=Deficient			
I NI NP D						
	IV. PLUMBING SYSTEM					
X X A. Plumb	ing Supply, Dis	tribution Syste	ems and Fixtures			
Location of M • Exterior of Comments: H undetectable machine hot components are beyond t or breaking a and/or should complete eva • Type = PE • Static Wa • Water line flushing of H inspection. • Operating scope of the inspectio. • Faucet at counter top. • There we the inspectio • Plumbing time of the i pipes to pro	f property by street cu Main Water Supply Valve structure on the left e Plumbing is an importan due to being within the and cold and icemaker are inspected. Private w he scope of this inspect fiter long periods of beind you have concern regulation be conducted p to priping ter Pressure Reading: ter Pressure Reading: ter pressure Reading: ter bridge is not tested ine upon move in. Leas the Hot and Cold wat inspection. Leaks we the kitchen sink is mis Recommend checkin re no leaks observed a on. supply pipes are not nspection. Recomment tect from hard freeze.	e: e: e: e: e: e: e: e: e: e:	cture. Some problems may be round, in floors or in the slab buring inspection. Only visible stems, water softeners and f re not tested due to possibil re marked in Red, marked a bly system, it is recommende for proper pressure. Reco ed in visible areas at the time shing machine is not with the visible areas at the time p, allowing faucet to rotate	 Washing e plumbing filter systems ity of leaking s "Deficient", ed a mmend ime of the in the e of the e over the he time of n area at the hose bib 		
Water meter location	Image: state of the	r shut off valve	Water pressure at left	elevation		

Main water shut off valve

Water pressure at left elevation





Drain line termination at rear left elevation

Pressere more than a set to open poper valve overcromes some pressere oppoper valve poper valve pressere oppoper valve poper valve pressere to an poper valve pressere oppoper valve to an poper valve to poper valve poper poper valve




TPR Valve operation

Tankless water heater located in garage


	1234 Texas Ave., Cypress, T.
NP=Not Present	D=Deficient
Therapy Equipment	
ir and draw it into the intake/su ly cleaned and maintained, ca e marked in Red, marked as "l	unit or tub. Intake ports can have high uction port, resulting in drowning. Hydro- n be the source of microbial and Deficient", and/or should you have omplete evaluation be conducted prior to the time of the inspection.
ocated in walls and buried und accessible gas supply connect "Deficient", and/or should you a complete evaluation be cond e Gas supply components of ut off valve is located on the ve trim is not present at the furnace gas lines are installe	only.
*	
ve decorative trim not present	Sediment trap cap blocked
	Therapy Equipment nall children unattended in the ir and draw it into the intake/si y cleaned and maintained, ca e marked in Red, marked as "I oment, it is recommended a co apy Tub was not present at the s line pressure inspection or p bocated in walls and buried und accessible gas supply connect 'Deficient", and/or should you a complete evaluation be cond e Gas supply components of it off valve is located on the ve trim is not present at the furnace gas lines are installed to deficient to be removed we decorative trim not present

Southern Star In	nspections, LLC		1234 Texas Ave.,	Cypress, TX
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
		V. APPLIANCES		
x	A. Dishwashers			
	dishwasher in other cycles and/or should you have co evaluation be conducted p • Dishwasher = Frigidaire • model# = FPID2498SF5 • serial# = KH92121978 • Dishwasher functione	e A d as intended at the time of t e and leaks were not present	arked in Red, marked as "De er, it is recommended that a c he inspection. Dishwasher	eficient", complete was ran
	B. Food Waste Dis	sposers		
	regarding the food waste of to close. • Disposer = Badger • model# = 1-87 • serial# = 19111307888 • Food Waste Disposer	arked in Red, marked as "Defic lisposer, it is recommended a c operated normally at time of d maintenance instructions.	complete evaluation be cond	ucted prior
x	C. Range Hood an	d Exhaust Systems		
	regarding the range exhauprior to close. • Vent Hood = Electrolux • model# = FHWC3660LS • serial# = HF94230024 • Range hood is presen	arke in Red, marked as "Deficie ist vent, it is recommended that A t and appears to be functioni following the manufacture ca	t a complete evaluation be co ing as intended at time of t	onducted he



Southern Star In	nspections, LLC		1234 Texas Ave.	, Cypress, T>
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	G. Garage Door Op	perators		
	and in good working order. consider upgrading your un opening controls upon mov you have concern regarding evaluation be conducted pr • Garage door openers of following the manufacture	Units should have electric e hit if these are not present. R e in. If items are marked in F g the garage door system, it for to close. Perated normally at the tir e care and maintenance in	ensitivity components in prop ye sensors. It is recommende ecommend reprogramming re Red, marked as "Deficient", a is recommended that a comp ne of the inspection. Recon structions. intended at the time of the i	ed that you emote door nd/or should blete nmend
	H. Dryer Exhaust S	Systems		
	 air flow. Inspection of Dryer marked as "Deficient", and/ recommended that a comp *Visually inspected acc 	Vent is of visual componen for should you have concern lete evaluation be conducted cessible areas of the dryer t the exterior rear left eleva	be of an inspection, and are r ts only. If items are marked ir regarding the dryer vent, it is d prior to close. vent only. Dryer exhaust flu- ation of the home. Recomm	n Red, ow is not
		Dryer vent termination		
	I. Other			
	Comments: • Refrigerator, washing r inspection.	nachine, and/or dryer were	e not present at the time of	the

Southern Star Inspections, LLC			1234 Texas Ave.,	Cypress,	ТХ	
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient		_	
I NI NP D						
VI. OPTIONAL SYSTEMS						
	A. Landscape Irri	gation (Sprinkler) Sys	stems			
	levels of moisture content system is inspected as pa spray from the sprinkler s fences, or outbuildings. It sprinkler water from enter as "Deficient", and/or sho recommended a complete • Sprinkler Control Box Zones = 10 (irrigation z • The irrigation main st located on the left eleva garage. • Testing the rain sense • Coverage of sprinklet	tems if not properly installed and t in the soil, can lead to different art of this inspection, system is te system should be directed away is unknown if a check valve is ir ring the main potable water syste ould you have any concern regar e evaluation be conducted prior = Rain Bird zones not mapped/labeled) hut off valve and homeowners ation of the home. The irrigation or is beyond the scope of the r heads next to structure, drive not spray directly on these are	tial foundation movement. If ested in the manual mode of from the structure and any of nstalled at the water meter t em. If items are marked in F rding the sprinkler system, it to close. service valves/anti-sipho on control panel is located inspection. eway, sidewalks, and fend	the sprinkler nly. Water decks, o prevent the Red, marked is on device are in the		
Main irrigation	shut off valve	owner service valves/anti-siphor	h Rain sensor not	tested		
		device		_		
	Type of Construction: Comments: If the swimmi are inspected in the man	ols, Spas, Hot Tubs, a ing pool is inspected as part of th ual mode only. iot present at the time of the ir	his inspection, the swimming	g pool timers		
	C. Outbuildings					
	Materials: Comments: • Out buildings are not	present at the time of the ins	pection.			
	X X D. Private Water Wells (A coliform analysis is recommended)					
		ent: ater well is present, a coliform a <mark>sent at the time of the inspecti</mark>				
REI 7-5 (05/4/2015)			Pa	ge 30 of 33		



Report Summary

STRUCTURAL	STRUCTURAL SYSTEMS				
Page 5 Item: B	Grading & Drainage	 Excessive moisture and/or standing water was observed at the left of the property at the time of the inspection. The grading should promote the flow of storm water away from the foundation and off the lot in a timely manner. Some options might be but not limited to: additional gutters, improved swale, surface drains, french drains, or sub surface drains. Gutters have construction and/or vegetation debris present that can possibly clog the gutter down spouts and cause moisture penetration. Recommend periodically cleaning all gutters so that water is diverted away from structure as intended. Check all. 			
Page 6 Item: C	Roof Covering Materials	 Construction/mud debris present at various locations of the roof covering at the time of the inspection. Check all. Damaged/torn shingle at the front elevation of the roof covering at the time of the inspection. Damaged shingles should either be properly sealed and or replaced to deter moisture intrusion and or further damage. Check all. 			
Page 7 Item: D	Roof Structures and Attics	• Access to the attic space above the study is not present at the time of the inspection. An attic that is greater that 30 sqft and has at least 30-inches of headroom should be readily accessible. Inspector observed higher than normal temperature difference at this location using thermal imaging camera. It appears batts and/or blown-in insulation is not installed within this attic space. Installing insulation so that all areas have an equal R-value has proven to save energy.			
Page 8 Item: E	Walls (Interior and Exterior)	 Seal all gaps where the exterior cladding material intersects with one another to deter moisture and insect intrusion. Some areas include but not limited to: exterior siding to stucco, stone to stucco. Check all. Seal around all gaps of electrical and/or plumbing penetrations through exterior walls to deter moisture and insect intrusion. Some areas include but not limited to: exterior light fixtures, electrical outlets, hose bibs, plumbing clean outs, vent terminations, gas lines, and A/C refrigerant lines. Check all. Seal all corners of shower tile and where tile meets tub/shower pan as needed. Recommend sealing around all plumbing fixtures in showers and tubs. Check all. 			
Page 10 Item: F	Ceilings and Floors	• Carpet flooring is not properly secure in place at the upstairs landing. This can be considered a trip hazard and is in need of repair. Check all.			
Page 10 Item: G	Doors (Interior and Exterior)	 Missing weatherstripping at the back door at the time of the inspection. Check all. Flush bolt at the back door is not functioning/unlocking as intended at the time of the inspection. Missing trim cover. Check all. Exterior door glass insert screw caps/covers are not present at the time of the inspection. Check all. Exterior door leading to the courtyard does not close tightly at the time of the inspection. Recommend adjusting doors so they are tight against strike plate when closed. Check all. 			
Page 12 Item: K	Porches, Balconies, Decks, and Carports	• Siding and/or siding trim material is not sealed/painted at the upper front porch at the time of the inspection. Check all.			
Page 13 Item: L	Other	 Driveway flatwork expansion joint is not cut/properly removed at the front elevation of the home at the time of the inspection. Check all. Fence picket is missing at the rear left elevation of the property at the time of the inspection. Check all. Soap dispenser or cover/cap is not present at the kitchen countertop at the time of the inspection. 			
ELECTRICAL	SYSTEMS				

Page 16 Item: B	Branch Circuits, Connected Devices, and Fixtures	 GFC (ground fault circuit interrupter) receptacles at the outdoor kitchen are not functioning/resetting at the time of the inspection. Ground Fault Circuit Interrupter (GFCI) receptacles are required in all wet areas. Required areas include: exterior, garage, kitchen backsplash, and bathrooms. Check all. Missing receptacle cover plate within the garage at the time of the inspection. Check all. Receptacles are not present at the right and left side of the kitchen island left at the time of the inspection. Light bulb is missing at the dining room light fixture at the time of the inspection. Recommend installing bulb and checking function of light fixture prior to closing on the home. Check all. Four way circuit/switches for the main kitchen lights are not wired properly at the time of the inspection. Switches have to be in a certain position for the other to function. These switches should be able to work independently of one another. The living room fan excessively wobbled/shook when operated at the time of the inspection. Recommend balance and/or tightening of the light kit. Recommend a complete system evaluation and repairs be made by a licensed Electrician prior to closing on the home. 		
HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS				
Page 19 Item: B	Cooling Equipment	 The A/C refrigerant line insulation at the <u>condensing unil</u> is damaged/torn. Refrigerant line exposed at the time of the inspection. Recommend repairing and/or replacing. Seal the gaps where the refrigerant lines enter the evaporater coil cabinet and where the condensing drain lines exit the <u>evaporator coil</u> cabinet to deter loss of conditioned air within the attic space. Check all. 		
Page 21 Item: C	Duct System, Chases, and Vents	 HVAC ducts within the upper attic space are in contact with one another at the time of the inspection. Contact between the ducts cools the surface and can cause harmful condensation to build up on the outside of the ductwork. Recommend separating with batts insulation. Check all. HVAC media filter is blocked by Furnace gas line and difficult to remove/install at the time of the inspection. 		
PLUMBING SYSTEM				
Page 23 Item: A	Plumbing Supply, Distribution Systems and Fixtures	 Plumbing supply pipes are not insulated at the rear elevation outdoor kitchen area at the time of the inspection. Recommend insulating all exterior plumbing pipes and hose bib pipes to protect from hard freeze. Check all. Low water pressure at the upstairs hallway bathroom shower fixture when tested at the time of the inspection. 		
Page 24 Item: B	Drains, Wastes, and Vents	 Drain stop is inoperable at the upstairs rear right elevation bathroom vanity at the time of the inspection. Leak present at the upstairs rear right elevation bathroom vanity drain line at the time of the inspection. Leak present at the upstairs hallway bathroom tub drain line at the time of the inspection. Water observed leaking below the bathroom/within the garage. Recommend a complete system evaluation and repairs made by a licensed Plumber prior to closing on the home. 		
Page 26 Item: E	Other	 Gas line valve decorative trim is not present at the exterior fireplace wall at the time of the inspection. Sediment traps for the furnace gas lines are installed against the attic floor/furnace decking boards making the caps difficult to be removed for future service. Check all. 		